

Work Order ID 84862

84862

Page 1

Tuesday, May 29, 2012 1:55:53 PM

Item ID: D2844-1

Accept

N900040100

Setup Start ***NS1***

Revision ID:

Item Name: Arm

Stop ***NS2***

Start Date: 5/28/2012 Start Qty: 2.00 ***2***

Cust Item ID:

Required Date: 5/29/2012 Req'd Qty: 2.00 ***2***

Customer: CU-DAR001

Reference: RMA RA111362 - RETURN

Approvals: Process Plan: MF Date: 12-05-29 Tooling:

Run Start ***NR1***

QC: Date: SPC (Y/N):

Stop ***NR2***

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

D2844	Rev A
-------	-------

100	0.00
-----	------

100

QC Memo 0.00

Quality Control INSPECT RA 111362 D2844-1 X 1 B74523

PART IS GOOD

110 Identify as per dwg & Stock Location: ST 265 0.00

110

Packaging Memo 0.00

Packaging ID AND STOCK UNDER NEW BATCH NUMBER

CLEAN THOROUGHLY BEFORE PACKAGING

120 QC21- Final Inspection - Work Order Release 0.00

120

QC Memo 0.00

Quality Control

2x SP
12-5-30

12/5/30

MF
12-05-30

Picklist Print

Tuesday, May 29, 2012 1:55:53 PM

Page 1

Work Order ID: 84862

Parent Item: D2844-1

Parent Item Name: Arm

Start Date: 5/28/2012

Required Date: 5/29/2012

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP: B00.11.01Removed P/O for Powder Coat - in house processEC

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D2844-1 Arm		Manufactured	No				Each	14.0000		2			

Location

Loc Qty

Loc Code

ST265

14

70541

1

74523

1

75063

12

2 x 74523 MF 12-05-29

RA 111362 D2844-1 B74523

Received @ Dart May 23rd, 2012
Inspected@ Dart May 23rd, 2012

Customer: Maritime Helicopters
Customer Contact: John Cox
Shipped from: Homer AK USA

Instructions for RA 111362 D2844-1 B74523

- Parts need no re working
- Needs new Paper work and labels
- Needs new batch number
- Put back in to stock with work order

Time Estimate = 1 HOUR ONLY (stores)

Departments Required: Stores (restocking)

Pictures Attached = NO

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!!**